



2311 SOUTH COLLINS, ARLINGTON, TX 76014-1224
817-460-2666

When retrieving your vehicle trouble codes, be aware that a trouble code represents a symptom identified by your vehicle's computer and not necessarily the failure of a specific part. Accurately determining the root cause of a trouble code requires more information, additional tools, and knowledge of diagnostic trees/charts. **We suggest you consult with a professional automotive repair facility.** They will have the equipment and knowledge necessary to fully troubleshoot the cause and recommend the needed repairs to your vehicle. **Any codes set on your vehicle should be cleared only by a professional technician and our team members will not clear these codes.**

Initial Information	
Trouble Code:	p0010
Vehicle:	2012 Chevrolet Camaro
	SS -- V8 6.2L vin J 376ci L99 FI MFI GAS OHV
Code Summary	
Code Definition:	"A" Camshaft Position Actuator Control Circuit/Open Bank 1
Possible Causes:	No Possible Causes Available
Reported Fixes:	No Reported Potential Fixes Available
Copyright: 2015	

Note: The reported potential fixes listed are suggestions only, and a fix is not guaranteed by performing any of the above potential solutions. We are providing this service to you as a convenience and for informational purposes only. **It is strongly recommended that you consult with a knowledgeable professional repair facility for proper diagnosis and repair of trouble code issues.** This information is provided without warranty and is subject to the Terms of Use posted at www.oreillyauto.com/TCS. Installation of parts on your vehicle will cause the parts to be non-returnable. Reproduction of this information or any portion thereof constitutes infringement of copyright.